



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed

[Handwritten signature]

Report Date: 04/02/2014

Mine Name: Peat Humas	Permit Number: S/023/0058	Mine Status: Inactive
Operator Name: Bonnie Birch Jensen	Inspection Date: 03/31/2014	Permit Fees: Delinquent
Inspector(s): Wayne Western	Inspection Time: 5:00 - 5:30 pm	Bond Amount: \$0
Attendee(s): none	Weather: cold cloudy	Bond Escalation:
Inspection Purpose: Follow up from enforcement		Prior Inspection: 08/14/2013

Conclusions and Recommendations

The Operator failed to reclaim the site. The Division should take action to remove that equipment on site and prevent damage to the environment.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documented that the site has not been reclaimed. Barge is still in the water and tanks are on shore. Posted an FTACO-2014042-04 on site. Operator failed to pay permit fees, post adequate bond and/or reclaim the site.			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>
3.	Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Barge is still in the water and poses a potential risk to the environment. Tanks and other equipment are on shore.			
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Operator failed to reclaim the stie			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

[Handwritten signature]

CC:


File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230058-JensenPeat/inspection/INSP03312014.pdf



Drag line still on site and other debris



Barge is still in the water



FTACO posted on site



Fuel tank on shore